

# Case Study

## RESTORATION AND EXPANSION

# Parking Lot Restoration and Expansion for Local Eastside Church

## The Challenge

A church in Anderson Township, Ohio, needed to address its aging and weathered parking lot. Potholes and standing water created safety risks for both vehicles and members of the congregation, while extensive pavement cracks tarnished the church's overall aesthetics. The damage was so extensive it limited both space and functionality of the 7,500-square-yard lot.

## Our Approach

Our team began with a thorough site evaluation to uncover both the visible and underlying causes of the damage. We designed a tailored plan that included blacktop repair and resurfacing to restore surface integrity and improve drainage, plus reconstruction of a concrete sidewalk leading to the church.

On every job — especially large, active community sites like this — safety comes first. Crews checked on one another throughout the project, ensuring traffic management and equipment operation were closely coordinated to protect both team members and visitors.

Despite the complexity of working around a busy facility, we completed the work efficiently and within schedule, minimizing downtime for church activities.

## The Result

Repairing structural issues allowed us to reconfigure the layout and add additional parking without expanding the footprint. The church now enjoys a smoother, safer lot with improved traffic flow and added capacity — enhancing the experience for congregation members and visitors alike.



**QUALITY**  
BLACKTOPPING + CONCRETE

[qualityblacktopping.com](http://qualityblacktopping.com)

513.844.2277