

# Case Study

## CHURCH PARKING LOT

### Restoring Safety and Confidence for a Church Community

Northern Kentucky

#### The Challenge

A church in Northern Kentucky was dealing with a deteriorating parking lot that posed safety risks for parishioners. The asphalt was crumbling, weeds and vines had overtaken sections of the surface, and parking spaces were improperly sized. Church leaders were unsure whether the lot could be repaired and needed to add ADA signage to meet code.

As a new customer, the church also wanted a partner they could trust to guide them through the best solution.

#### Our Approach

Quality Blacktopping + Concrete began by clearing overgrown vegetation and restoring the surface. The team then completed an asphalt overlay, refreshing the lot without the cost and disruption of full replacement. The team installed new parking lines to improve organization and create additional spaces and added ADA parking signs to ensure code compliance.

Throughout the project, the team focused on efficiency, quality workmanship, and clear communication.

#### The Result

The church gained a safer, more attractive, and easier-to-navigate parking lot that better serves parishioners and visitors. The improved layout and fresh surface enhanced both function and appearance while extending the life of the pavement.

The client was highly satisfied and has already recommended Quality Blacktopping + Concrete to other churches and parishioners.



“The transformation was incredible. We’ve already recommended Quality to other churches because we trust the work and the team behind it.”

